



- NOTES – 1. WHERE EXCESSIVE CUT OCCURS, RAMP CUT DIAGONALLY ACROSS ALLOTMENT.  
 2. DRIVEWAYS TO BE LOCATED TO ENSURE THAT BATTERS TO ACCESS RAMP DO NOT ENCROACH INTO ADJOINING LOTS



**GREATER DANDENONG**

**DRIVEWAYS  
ACCESS RAMPS TO ALLOTMENTS**

LAST UPDATED – SEPTEMBER 2014

---

INFRASTRUCTURE PLANNING

**SD 309–A**